IDAHO DEPARTMENT OF HEALTH & WELFARE

C.L. "BUTCH" OTTER – Governor
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T – Chief
BUREAU OF FACILITY STANDARDS
3232 Elder Street
P.O. Box 83720
Boise, Idaho 83720-0009
PHONE: (208) 334-6626
FAX: (208) 364-1888
E-mail: fsb@dhw.idaho.gov

October 26, 2012

Diana Ray, Administrator
Meridian Care & Rehabilitation Center
1351 West Pine Avenue
Meridian, ID 83642

License #: RC-546

Dear Ms. Ray:

On August 30, 2012, a Fire Life Safety Survey was conducted at Meridian Care & Rehabilitation Center. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level:

- Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire Safety and Construction Program, at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY
Health Facility Surveyor
Facility Fire Safety & Construction Program

TB/lj

c: Mark Grimes, Supervisor, Facility Fire Safety & Construction Program

IDAHO DEPARTMENT OF
HEALTH & WELFARE

C.L. "BUTCH" OTTER, Governor
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T – Chief
BUREAU OF FACILITY STANDARDS
3232 Elder Street
P.O. Box 83720
Boise, Idaho 83720-0009
PHONE: (208) 334-6626
FAX: (208) 364-1888
E-mail: fsb@dhw.idaho.gov

September 4, 2012

Diana Ray, Administrator
Meridian Care & Rehabilitation Center
1351 West Pine Avenue
Meridian, Idaho 83642

Dear Ms. Ray:

On August 30, 2012, a Fire Life Safety Survey was conducted at Meridian Care & Rehabilitation Center. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by September 30, 2012.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK P. GRIMES
Supervisor
Facility Fire Safety & Construction Program

MPG/lj

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - ENTIRE BUILDING B. WING _____	(X3) DATE SURVEY COMPLETED
	13R546		08/30/2012

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
MERIDIAN CARE & REHABILITATION CENTER	1351 WEST PINE AVENUE MERIDIAN, ID 83642

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
R 000	Initial Comments The facility was found to be in substantial compliance with the life safety code requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard life safety code survey conducted on August 30, 2012. The surveyor conducting the survey was: Taylor Barkley Health Facility Surveyor Facility Fire Safety & Construction	R 000		

Bureau of Facility Standards

TITLE (X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

IDAHO DEPARTMENT OF
HEALTH & WELFARE

MEDICAID L & C – RALF PROGRAM
P.O. Box 83720
Boise, ID 83720-0036
(208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING
Non-Core Issues Punch List

Facility Name	Physical Address	Phone Number
Meridian Care and Rehab	1351 W Pine Ave	208-888-7049
Administrator	**City**	**ZIP Code**
Diana Ray	Meridian Id	83642
Survey Team Leader	**Survey Type**	**Survey Date**
Taylor Barkley		8-30-12

NON-CORE ISSUES

ITEM #	RULE # 16.03.22	DESCRIPTION	DATE RESOLVED	L & C USE
1	410.02	The facility did not conduct one drill per shift per Quarter.	10-5-12	TB
2	250.01	The south east end of the roof is missing multiple shingles and an area that is approximately two foo by three feet that is missing the shingling.	10-5-12	TB
3.	405.05	On the southwest side of the facility There are two 4 x 8 soffit sheets with water damage that are hanging down from the framing.	10-20-12	TB

Response Required Date	Signature of Facility Representative	Date Signed
9-30-12		8/30/12