



C.L. "BUTCH" OTTER - Governor
RICHARD M. ARMSTRONG -- Director

IDAHO DEPARTMENT OF

HEALTH & WELFARE

DEBBY RANSOM, R.N., R.H.I.T. - Chief
BUREAU OF FACILITY STANDARDS
3232 Elder Street
P.O. Box 83720
Boise, Idaho 83720-0009
PHONE: (208) 334-6626
FAX: (208) 364-1888
E-mail: fsb@dhw.idaho.gov

July 31, 2015

Melinda Weber, Administrator
The Renaissance at Coeur d'Alene
2772 West Avante Loop
Coeur d'Alene, ID 83815

Dear Ms. Weber:

On July 22, 2015, a Fire Life Safety Survey was conducted at The Renaissance at Coeur d'Alene. The facility was found to be providing a safe environment for its residents.


The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK P. GRIMES, Supervisor
Facility Fire Safety & Construction Program

MPG/lj
Enclosure



IDAHO DEPARTMENT OF
HEALTH & WELFARE

C.L. "BUTCH" OTTER – GOVERNOR
RICHARD M. ARMSTRONG – DIRECTOR

TAMARA PRISOCK – ADMINISTRATOR
DIVISION OF LICENSING & CERTIFICATION
JAMIE SIMPSON – PROGRAM SUPERVISOR
RESIDENTIAL ASSISTED LIVING FACILITIES PROGRAM
P.O. Box 83720
Boise, Idaho 83720-0009
Email: ralf@dhw.idaho.gov
PHONE (208) 364-1962
FAX (208) 364-1888

Tech Assist Items Survey Date: 07/22/2015

16.03.22.415.05. Automatic Fire Extinguishing System Service and Testing.

All automatic fire extinguishing systems must be inspected, tested, and serviced at least annually by a sprinkler system contractor licensed by the Idaho State Fire Marshal's office.

Post indicator valve is showing that system may not be fully open. Recommendation to contact fire department and vendor to work on indicator window. All sprinkler reports indicate full operation without any subsequent issues.