



IDAHO DEPARTMENT OF  
HEALTH & WELFARE

C.L. "BUTCH" OTTER -- Governor  
RICHARD M. ARMSTRONG -- Director

TAMARA PRISOCK -- ADMINISTRATOR  
DIVISION OF LICENSING & CERTIFICATION  
DEBRA RANSOM, R.N., R.H.I.T., Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, ID 83720-0009  
PHONE 208-334-6626  
FAX 208-364-1888

November 02, 2015

Viorel Boeru, Administrator  
Advanced Assisted Living  
601 West Blaine Avenue  
Nampa, ID 83651

License #: RC-943

Dear Mr. Boeru:

On August 20, 2015, a Fire Life Safety Survey was conducted at Advanced Assisted Living. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level:

- Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Sam Burbank, Health Facility Surveyor, Facility Fire Safety and Construction Program, at (208) 334-6626, option 3.

Sincerely,

Sam Burbank  
Health Facility Surveyor  
Facility Fire Safety & Construction Program

SB/lj



C.L. "BUTCH" OTTER - Governor  
RICHARD M. ARMSTRONG - Director

IDAHO DEPARTMENT OF  
HEALTH & WELFARE

DEBBY RANSOM, R.N., R.H.I.T. - Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, Idaho 83720-0009  
PHONE: (208) 334-6626  
FAX: (208) 364-1888  
E-mail: [fsb@dhw.idaho.gov](mailto:fsb@dhw.idaho.gov)

August 27, 2015

Viorel Boeru, Administrator  
Advanced Assisted Living  
601 West Blaine Avenue  
Nampa, ID

Dear Mr. Boeru:

On August 20, 2015 a Fire Life Safety survey was conducted at Advanced Assisted Living. The facility was found to be providing a safe environment and safe, effective care to residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that three (3) non-core issue deficiencies were identified on the punch list and one was identified as a repeat punch. As explained during the exit conference, the completed punch list form and accompanying proof of resolution (e.g., receipts, photographs, policy updates, etc.) needs to be submitted to our office no later than September 21, 2015.

Please ensure the facility is continually monitoring its compliance with state rules, as further repeat punches identified during future surveys could result in enforcement actions including:


- a. Issuance of a provisional license
- b. Limitations of admissions to the facility
- c. Hiring a consultant who submits periodic reports to the Licensing and Certification
- d. Civil monetary penalties

Our staff is available to answer questions and to assist you in identifying appropriate corrections to avoid further enforcement actions. Should you require assistance or have any questions about our visit, please contact us at (208) 334-6626. Thank you for your continued participation in the Idaho Residential Assisted Living Facility (RALF) Program.

Sincerely,

MARK P. GRIMES  
Program Supervisor  
Facility Fire Safety & Construction Program

Enclosure



# IDAHO DEPARTMENT OF HEALTH & WELFARE

C.L. "BUTCH" OTTER – GOVERNOR  
RICHARD M. ARMSTRONG – DIRECTOR

TAMARA PRISOCK – ADMINISTRATOR  
DIVISION OF LICENSING & CERTIFICATION  
JAMIE SIMPSON – PROGRAM SUPERVISOR  
RESIDENTIAL ASSISTED LIVING FACILITIES  
PROGRAM

P.O. Box 83720  
Boise, Idaho 83720-0009  
Email: [ralf@dhw.idaho.gov](mailto:ralf@dhw.idaho.gov)  
PHONE (208) 364-1962  
FAX (208) 364-1888

## Punch Items

Survey Date: 08/20/2015

### 16.03.22.415.05. Automatic Fire Extinguishing System Service and Testing.

All automatic fire extinguishing systems must be inspected, tested, and serviced at least annually by a sprinkler system contractor licensed by the Idaho State Fire Marshal's office.

Sprinkler pendants in garage are loaded with lint

### 16.03.22.161.01. Policy on Smoking

The facility must develop written rules governing smoking. These rules must be made known to all facility personnel, residents, and the visiting public.

Administrator smoking in garage

### 16.03.22.405.05. Structure. Maintenance. Equipment to Assure Safety.

The facility must be structurally sound, maintained, and equipped to assure the safety of residents, personnel, and the public including:

1) Water temps in facility at 126 degrees - can't be higher than 120 degrees

2) Office area locked - not open for inspection

