



IDAHO DEPARTMENT OF  
HEALTH & WELFARE

C.L. "BUTCH" OTTER – Governor  
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T. – Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, Idaho 83720-0009  
PHONE: (208) 334-6626  
FAX: (208) 364-1888  
E-mail: [fsb@dhw.idaho.gov](mailto:fsb@dhw.idaho.gov)

January 2, 2013

Sheila Oetting, Administrator  
Bridge At Post Falls  
515 North Garden Plaza Court  
Post Falls, ID 83854

License #: Rc-976

Dear Ms. Oetting:

On November 9, 2012, a Fire Life Safety Survey was conducted at Post Falls Retirement Llc - Db a - The Bridge At Post Falls. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

- Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Tom Mroz, Health Facility Surveyor, Facility Fire Safety and Construction Program, at (208) 334-6626.

Sincerely,

Tom Mroz  
Health Facility Surveyor  
Facility Fire Safety & Construction Program

TM/nw

c: Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



IDAHO DEPARTMENT OF  
HEALTH & WELFARE

C.L. "BUTCH" OTTER, Governor  
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T – Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, Idaho 83720-0009  
PHONE: (208) 334-6626  
FAX: (208) 364-1888  
E-mail: [fsb@dhw.idaho.gov](mailto:fsb@dhw.idaho.gov)

November 16, 2012

Sheila Oetting, Administrator  
Bridge at Post Falls  
515 North Garden Plaza Court  
Post Falls, ID 83854

Dear Ms. Oetting:

On November 9, 2012, a Fire Life Safety Survey was conducted at Post Falls Retirement Llc - DbA - The Bridge At Post Falls. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by December 9, 2012.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

A handwritten signature in black ink, appearing to read "Mark P. Grimes". The signature is fluid and cursive, with a long horizontal stroke extending to the right.

MARK P. GRIMES, Supervisor  
Facility Fire Safety & Construction Program

MPG/dmj  
Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>13R976</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01 - ENTIRE BUILDING</b> B. WING _____	(X3) DATE SURVEY COMPLETED  <b>11/09/2012</b>
NAME OF PROVIDER OR SUPPLIER  <b>BRIDGE AT POST FALLS</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>515 NORTH GARDEN PLAZA COURT POST FALLS, ID 83854</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
R 000	<p><b>Initial Comments</b></p> <p>The facility was found to be in substantial compliance with the life safety code requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard life safety code survey conducted on November 9, 2012.</p> <p>The surveyor conducting the survey was:</p> <p>Tom Mroz CFI-II Health Facility Surveyor Facility Fire Safety &amp; Construction</p>	R 000		

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

