



C.L. "BUTCH" OTTER – Governor  
RICHARD M. ARMSTRONG – Director

IDAHO DEPARTMENT OF  
**HEALTH & WELFARE**

DEBBY RANSOM, R.N., R.H.I.T. – Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, Idaho 83720-0009  
PHONE: (208) 334-6626  
FAX: (208) 364-1888  
E-mail: [fsb@dhw.idaho.gov](mailto:fsb@dhw.idaho.gov)

September 19, 2013

Mark Maxfield, Administrator  
The Cottages of McCall  
Po Box 1973  
McCall, ID 83638

Dear Mr. Maxfield:

On September 13, 2013, a Fire Life Safety Survey was conducted at Cottage Investors III, LLC-- The Cottages of McCall. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

A handwritten signature in black ink, appearing to read 'Mark P. Grimes', with a long horizontal flourish extending to the right.

MARK P. GRIMES, Supervisor  
Facility Fire Safety & Construction Program

MPG/lj  
Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>13R949</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01 - ENTIRE BUILDING</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>09/13/2013</b>
--	---	---	---

NAME OF PROVIDER OR SUPPLIER  <b>COTTAGE INVESTORS, LLC DBA THE COTTA</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>700 REEDY LANE MC CALL, ID 83638</b>
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
R 000	<p><b>Initial Comments</b></p> <p>The facility was found to be in substantial compliance with the life safety code requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard life safety code survey conducted on September 13, 2013.</p> <p>The surveyor conducting the survey was:</p> <p>Taylor Barkley Health Facility Surveyor Facility Fire Safety &amp; Construction</p>	R 000		

Bureau of Facility Standards LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------