



IDAHO DEPARTMENT OF
HEALTH & WELFARE

C.L. "BUTCH" OTTER – Governor
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T. – Chief
BUREAU OF FACILITY STANDARDS
3232 Elder Street
P.O. Box 83720
Boise, Idaho 83720-0009
PHONE: (208) 334-6626
FAX: (208) 364-1888
E-mail: fsb@dhw.idaho.gov

March 15, 2013

Lisa Moore, Administrator
Midland Manor
9766 West Mossy Cup Street
Boise, ID 83709

License #: RC-854

Dear Mrs. Moore:

On February 1, 2013, a Fire Life Safety Survey was conducted at Midland Manor. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

- Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact me at (208) 334-6626.

Sincerely,

Tom Mroz
Health Facility Surveyor
Facility Fire Safety & Construction Program

TM/nm

c: Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



IDAHO DEPARTMENT OF
HEALTH & WELFARE

C.L. "BUTCH" OTTER, Governor
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T – Chief
BUREAU OF FACILITY STANDARDS
3232 Elder Street
P.O. Box 83720
Boise, Idaho 83720-0009
PHONE: (208) 334-6626
FAX: (208) 384-1888
E-mail: fsb@dhw.idaho.gov

February 5, 2013

Lisa Moore, Administrator
Midland Manor
9766 West Mossy Cup Street
Boise, ID 83709

Dear Mrs. Moore:

On February 1, 2013, a Fire Life Safety follow-up survey was conducted at Midland Manor. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by March 1, 2013.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK P. GRIMES, Supervisor
Facility Fire Safety & Construction Program

MPG/mm
Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 13R854	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - BUILDING 1 B. WING _____	(X3) DATE SURVEY COMPLETED 02/01/2013
NAME OF PROVIDER OR SUPPLIER MIDLAND MANOR		STREET ADDRESS, CITY, STATE, ZIP CODE 9 SOUTH MIDLAND BOULEVARD NAMPA, ID 83651		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
R 000	<p>Initial Comments</p> <p>A follow-up survey was performed. The facility was found to be in substantial compliance with the fire and life safety requirements of IDAPA 16.03.22 Residential Care or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on February 1, 2013..</p> <p>The surveyor conducting the survey was:</p> <p>Tom Mroz CFI-II Health Facility Surveyor Facility Fire/Life Safety & Construction Program</p>	R 000		

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

