



IDAHO DEPARTMENT OF  
HEALTH & WELFARE

C.L. "BUTCH" OTTER – Governor  
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T – Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, Idaho 83720-0009  
PHONE: (208) 334-6626  
FAX: (208) 364-1888  
E-mail: [fsb@dhw.idaho.gov](mailto:fsb@dhw.idaho.gov)

June 7, 2011

Ione Springer, Administrator  
Apple Valley Residential Care  
715 North Butte Avenue  
Emmett, Idaho 83617

License #: RC-445

Dear Ms. Springer:

On April 29, 2011, a Fire Life Safety Survey was conducted at Apple Valley Residential Care. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level:

- Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire Safety and Construction Program, at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY  
Health Facility Surveyor  
Facility Fire Safety & Construction Program

TB/lj

c: Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



IDAHO DEPARTMENT OF  
HEALTH & WELFARE

C.L. "BUTCH" OTTER, Governor  
RICHARD M. ARMSTRONG - Director

DEBBY RANSOM, R.N., R.H.I.T. - Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, Idaho 83720-0009  
PHONE: (208) 334-6626  
FAX: (208) 364-1888  
E-mail: [fsb@dhw.idaho.gov](mailto:fsb@dhw.idaho.gov)

May 6, 2011

Ione Springer, Administrator  
Apple Valley Residential Care  
715 North Butte Avenue  
Emmett, Idaho 83617

Dear Ms. Springer:

On April 29, 2011, a Fire Life Safety Survey was conducted at Apple Valley Residential Care. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by May 31, 2011.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

A handwritten signature in black ink, appearing to read 'MPG', with a long, sweeping horizontal line extending to the right.

MARK P. GRIMES  
Supervisor  
Facility Fire Safety & Construction Program

MPG/lj

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>13R445</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01 - ENTIRE BUILDING</b> B. WING _____	(X3) DATE SURVEY COMPLETED  <b>04/29/2011</b>
NAME OF PROVIDER OR SUPPLIER  <b>APPLE VALLEY RESIDENTIAL CARE</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>715 NORTH BUTTE AVENUE EMMETT, ID 83617</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
R 000	Initial Comments  The facility was found to be in substantial compliance with the life safety code requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard life safety code survey conducted on April 29, 2011.  The surveyor conducting the survey was:  Taylor Barkley Health Facility Surveyor Facility Fire Safety & Construction	R 000		

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

