

HEALTH & WELFARE

DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-009 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@dhw.idaho.gov

October 25, 2012

Jill Woolsey, Administrator Brookside Landing 431 Johnson Avenue Orofino, ID 83544

Dear Ms. Woolsey:

On October 17, 2012, a Fire Life Safety Survey was conducted at Brookside Landing. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK P. GRIMES

Supervisor

Facility Fire Safety & Construction Program

MPG/lj

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: 01 - ENTIRE BUILDING A. BUILDING B. WING 13R680 10/17/2012 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **431 JOHNSON AVENUE BROOKSIDE LANDING** OROFINO, ID 83544 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE DATE (X4) ID (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PRÉFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the life safety code requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard life safety code survey conducted on October 17, 2012. The surveyor conducting the survey was: Taylor Barkley Health Facility Surveyor Facility Fire Safety & Construction

Bureau of Facility Standards

TITLE

(X6) DATE