



IDAHO DEPARTMENT OF
HEALTH & WELFARE

C.L. "BUTCH" OTTER – Governor
RICHARD M. ARMSTRONG – Director

DEBRA RANSOM, R.N., R.H.I.T., Chief
BUREAU OF FACILITY STANDARDS
3232 Eider Street
P.O. Box 83720
Boise, ID 83720-0009
PHONE 208-334-6626
FAX 208-364-1888

August 15, 2014

Rena Oswald, Administrator
Eastern Idaho Regional Medical Center-- TCU
PO Box 2077
Idaho Falls, ID 83403-2077

Provider #: 135115

RE: FACILITY FIRE SAFETY & CONSTRUCTION SURVEY REPORT COVER LETTER

Dear Ms. Oswald:

On **August 6, 2014**, a Facility Fire Safety and Construction survey was conducted at Eastern Idaho Regional Medical Center-- TCU by the Bureau of Facility Standards/Department of Health & Welfare to determine if your facility was in compliance with State Licensure and Federal participation requirements for nursing homes participating in the Medicare and/or Medicaid programs. Your facility was found to be in substantial compliance with Federal regulations during this survey.

Enclosed is a Statement of Deficiencies/Plan of Correction, Form CMS-2567, which states that the facility complies with the requirements of CFR 42, 483.70(a) of the federal requirements, and a copy of the State fire safety Statement of Deficiencies form, which states the facility complies with the Fire Protection Standards of the Rules and Minimum Standards for Skilled Nursing and Intermediate Care Facilities. This form is for your records only and does not need to be returned.

Thank you for the courtesies extended to us during the survey. If you have any questions, please contact this office at (208) 334-6626.

Sincerely,

Mark P. Grimes, Supervisor
Facility Fire Safety and Construction

MPG/lj
Enclosures

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 08/13/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 135115	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/06/2014
--	---	--	---

NAME OF PROVIDER OR SUPPLIER EASTERN IDAHO REGIONAL MEDICAL CENTI	STREET ADDRESS, CITY, STATE, ZIP CODE PO BOX 2077 IDAHO FALLS, ID 83403
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

K 000	<p>INITIAL COMMENTS</p> <p>This facility is Type I construction and has multiple stories. The TCU is located on the sixth floor. Fire protection features include a complete automatic fire extinguishing system throughout; and a fire alarm/smoke detection system. Currently the facility is licensed for 16 beds and had a census of seven on the day of the survey.</p> <p>The facility was found to be in substantial compliance during the annual fire/life safety survey conducted on August 6, 2014. The facility was surveyed under the LIFE SAFETY CODE, 2000 Edition, Existing Health Care Occupancy and in accordance with 42 CFR 483.70.</p> <p>The Survey was conducted by:</p> <p>Sam Bubank Health Facility Surveyor Facility Fire Safety and Construction</p>	K 000		
-------	--	-------	--	--

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 135115	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 08/06/2014
NAME OF PROVIDER OR SUPPLIER EASTERN IDAHO REGIONAL MEDICAL CENTER -		STREET ADDRESS, CITY, STATE, ZIP CODE PO BOX 2077 IDAHO FALLS, ID 83403		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>16.03.02 INITIAL COMMENTS</p> <p>The Administrative Rules of the Idaho Department of Health and Welfare, Skilled Nursing and Intermediate Care Facilities are found in IDAPA 16, Title 03, Chapter 2.</p> <p>This facility is Type I construction and has multiple stories. The TCU is located on the sixth floor. Fire protection features include a complete automatic fire extinguishing system throughout, and a fire alarm/smoke detection system. Currently the facility is licensed for 16 beds and had a census of seven on the day of the survey.</p> <p>The facility was found to be in substantial compliance during the annual fire/life safety survey conducted on August 6, 2013. The facility was surveyed under the LIFE SAFETY CODE, 2000 Edition, Existing Health Care Occupancy, in accordance with 42 CFR 483.70 and IDAPA 16.03.02, Rules and Minimum Standards for Skilled Nursing and Intermediate Care Facilities.</p> <p>The survey was conducted by:</p> <p>Sam Burbank Health Facility Surveyor Facility Fire Safety and Construction</p>	C 000		

Idaho form

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE